



# Construction Photos

January 12, 2019 — February 16, 2019

## EB I-94 West of Grand River Site Work Overview



**EB I-94 SE Corner of Cooper Street Rock Drilling**



**EB I-94 SW Corner of Cooper Street Rock Drilling**





**EB I-94 SE Corner of Cooper Street Rock Drilling**



**EB I-94 SW Corner of Cooper Street Rock Drilling**





**EB I-94 West of Grand River Working on Pier**



**EB I-94 West of Grand River Stripping Pier Cap Forms**





## EB I-94 West of Grand River Site Work Overview



## EB I-94 West of Grand River Site Work Overview





**EB I-94 West Abutment Tying Reinforcing Steel**



**EB I-94 West of Grand River Site Work Overview**

